



HYPER KROME Ag Exclusive Clear Set

Spray Topcoat Clear after spraying HYPER KROME Ag.

HTPER KROME Ag Exclusive Clear Set is the most suitable for HYPER KROME Ag.

◆CONTENTS

- HYPER KROME Ag Exclusive Clear : 1kg
- HYPER KROME Ag Hardener for Clear : 500g
- HYPER KROME Ag Thinner for Clear : 200g

◆HOW TO USE

Spray Topcoat Clear after HYPER KROME Ag complete drying.

The discharge of a gun should be down and it should be mist as long as you can.

Take three – five minutes for interval and repeat it three – four times.

Take interval for about 1 hour as forced drying of 60°C~70°C, furthermore leave for 3 – 4 hours under normal temperature, or just leave for about 24 hours under normal temperature after the last spray of Topcoat Clear..

After that, spray again with semi-wet and take interval 5 – 10 minutes furthermore, and go to the final spray with wet again.

◆DRYING TIME AFTER ALL PROCESS

Set to touch after 6 hours with normal temperature 20°C or 35 minutes with forced drying 60°C.

Cool down to normal temperature after complete drying and available to polish after 1 hour from cooling down.

◆COMPOSITION

- 100 HYPER KROME Ag Exclusive Clear
- 50 HYPER KROME Ag Hardener for Clear
- 10 HYPER KROME Ag Thinner for Clear

HYPER KROME Ag Exclusive Clear 2 : 1 Hardener. And combine Thinner of 10% with the Clear.

Signal Inc., SHOW UP Division

2-6-8 Aoshinke Mino Si, Osaka Japan 562-0024 Tel. 072-727-7123 Fax. 072-727-2678 Email. info@showup.jp

<http://www.showup.jp/Ag.html>

