



Aurora Space PhANTOM

Phantom Operation Manual

Thank you very much for buying our product.

1. Spraying of base colors	First spraying should be thin and uniform. Spray gradually strongly and spray dryly by an air blow from the second painting.			
	dilution ratio of thinner	80~100%	discharge quantity	turning 2.5~3.5 rounds
	air pressure	1.5~2.5mpa	distance	15~25cm
2. Spraying Phantom	Please spray to ignore color mottles as usual. Spray repeatedly after drying the surface by an air blow and the luster of the surface is lost.			
	dilution ratio of thinner	80~100%	discharge quantity	turning 2.5~3 rounds
	air pressure	2~2.5mpa	distance	15~20cm
3. Finishing Phantom	Finish spraying approximately 2 times because you may miss color mottles as the luster is lost even though color mottles mostly hardly come out after spraying each color as usual.			
	dilution ratio of thinner	80-100%	discharge quantity	turning 2.5~3 rounds
	air pressure	2~2.5mpa	distance	20~25cm
4. Top coat clear	Finish spraying top coat clear after approximately 10 minutes interval.			

Cautions

When you handle this product, make sure to use rubber gloves and glasses to protect your skin and eyes.
 In case it gets into your eyes, wash them with running water thoroughly and see a doctor.
 In case it comes into contact with your skin, please wash it thoroughly until the slimy feeling is gone.
 If you feel pain and something amiss, ask a doctor for instruction.
 After use, make sure to close the lid firmly and leave it where it dark and cold, away from the direct sun.
 Please keep it away from young children.



2-6-8 Aoshinke Mino Si Osaka, Japan 562-0024
 Tel. 072-727-7123 Fax. 072-727-2678 Email. info@showup.jp